



photo 1: East corner of the location facing west.



photo 2: Facing northwest along the perimeter fence around the location.



Photo 3: Facing west towards the location.



Photo 4: Weed growth (kochia) throughout the location..




Photo 5: Center of the location facing north.



Photo 6: Center of the location facing west.



Photo 7: Center of the location facing south.



Photo 8: Center of the location facing east.



Photo 9: North side of the location facing south.



Photo 10: West side of the location facing east.



Photo 11: Fence at the west side of the location is not maintained.



Photo 12: Surrounding undisturbed vegetation outside of the location.