



photo 1: Facing southwest towards the location along the access road.



photo 2: Facing southwest towards the location.



Photo 3: Center of the location facing north.



Photo 4: Center of the location facing west.



Photo 5: Center of the location facing south.



Photo 6: Center of the location facing east.



Photo 7: Area of subsidence noticed at the location. Lat/Long:38.99611/-103.27708.



Photo 8: Another area of subsidence noticed at the location. Lat/Long:38.99608/-103.27706.



Photo 9: Weed growth (kochia) throughout the location.



Photo 10: View of the vegetation cover at the location.