

Iles Dome Unit 22

Inspection# 673402823

Free product around wellhead and in background.



Stained soil.




Free product mingled with snowmelt.



Free product mingled with snow melt.



Close up of free product mixed with snow melt.



Close up of free product mixed with snow melt.



Free product mixed with snow melt.

