

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/11/2016

Document Number:

675202400

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334508	334508	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Conklin, Curtis		curtis.conklin@state.co.us	Area 132 Inspector

Compliance Summary:QtrQtr: NWSE Sec: 11 Twp: 9S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/05/2014	675200341			SATISFACTORY			No
08/05/2014	675200338			SATISFACTORY			No

Inspector Comment:Inspection to pass final reclamation on AL wells only. No evidence of wells on location.**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
159184	UIC DISPOSAL	AC	06/13/2007		-	MCDANIEL 11-16 SWD	AC	<input type="checkbox"/>
221743	WELL	DA	07/25/1985	DA	077-08345	MCDANIEL 1-11	DA	<input type="checkbox"/>
221964	WELL	PR	09/05/2007	GW	077-08566	MCDANIEL 11-10	PR	<input type="checkbox"/>
273822	WELL	PR	12/01/2014	GW	077-08818	MC DANIEL 11-8	PR	<input type="checkbox"/>
273823	WELL	PR	06/01/2011	GW	077-08817	MCDANIEL 11-9	PR	<input type="checkbox"/>
273824	WELL	SI	03/06/2014	DSPW	077-08815	MCDANIEL 11-16	SI	<input type="checkbox"/>
273825	WELL	AL	09/23/2005	LO	077-08816	MCDANIEL 11-15	AL	<input checked="" type="checkbox"/>
274048	WELL	AL	08/03/2006	LO	077-08827	MCDANIEL 11-14	AL	<input checked="" type="checkbox"/>
296115	WELL	AL	06/28/2011	LO	077-09651	MCDANIEL 11-16B	AL	<input checked="" type="checkbox"/>
296116	WELL	PR	12/14/2010	GW	077-09652	MCDANIEL 11-16A	PR	<input type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

296117	WELL	AL	10/10/2012	LO	077-09653	MCDANIEL 11-15C	AL	<input checked="" type="checkbox"/>
296118	WELL	PR	07/01/2011	GW	077-09654	MCDANIEL 11-9C	PR	<input type="checkbox"/>
296119	WELL	PR	07/01/2011	GW	077-09655	MCDANIEL 11-9B	PR	<input type="checkbox"/>
296120	WELL	PR	06/26/2010	GW	077-09650	MCDANIEL 11-10C	PR	<input type="checkbox"/>
296121	WELL	PR	06/18/2010	GW	077-09649	MCDANIEL 11-10A	PR	<input type="checkbox"/>
296122	WELL	AL	10/10/2012	LO	077-09648	MCDANIEL 11-15A	AL	<input checked="" type="checkbox"/>
296123	WELL	AL	10/10/2012	LO	077-09647	MCDANIEL 11-15B	AL	<input checked="" type="checkbox"/>
296124	WELL	PR	12/13/2010	GW	077-09646	MCDANIEL 11-10B	PR	<input type="checkbox"/>
297881	WELL	PR	10/01/2012	GW	077-09709	MCDANIEL 11-9A	PR	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 334508

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 273825 Type: WELL API Number: 077-08816 Status: AL Insp. Status: AL

Facility ID: 274048 Type: WELL API Number: 077-08827 Status: AL Insp. Status: AL

Facility ID: 296115 Type: WELL API Number: 077-09651 Status: AL Insp. Status: AL

Facility ID: 296117 Type: WELL API Number: 077-09653 Status: AL Insp. Status: AL

Facility ID: 296122 Type: WELL API Number: 077-09648 Status: AL Insp. Status: AL

Facility ID: 296123 Type: WELL API Number: 077-09647 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Inspector Name: CONKLIN, CURTIS

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass

Well Release on Active Location ☐

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT