

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2016

Document Number:

666801819

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	286769	334713	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

**Compliance Summary:**QtrQtr: SENW Sec: 5 Twp: 7S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/19/2008	200200995	PR	PR	SATISFACTORY			No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
284915	WELL	PR	05/31/2006	GW	045-12302	STUBBS RWF 312-5	PR	<input checked="" type="checkbox"/>
284917	WELL	PR	05/31/2006	GW	045-12301	STUBBS RWF 321-5	PR	<input checked="" type="checkbox"/>
286731	WELL	PR	06/18/2008	GW	045-12736	STUBBS RWF 422-5	PR	<input checked="" type="checkbox"/>
286732	WELL	PR	06/18/2008	GW	045-12735	STUBBS RWF 12-5	PR	<input checked="" type="checkbox"/>
286733	WELL	PR	06/18/2008	GW	045-12734	STUBBS RWF 11-5	PR	<input checked="" type="checkbox"/>
286759	WELL	PR	06/13/2007	GW	045-12733	STUBBS RWF 322-5	PR	<input checked="" type="checkbox"/>
286760	WELL	PR	06/18/2008	GW	045-12732	STUBBS RWF 522-5	PR	<input checked="" type="checkbox"/>
286761	WELL	PR	06/18/2008	GW	045-12731	STUBBS RWF 22-5	PR	<input checked="" type="checkbox"/>
286762	WELL	PR	06/18/2008	GW	045-12730	STUBBS RWF 412-5	PR	<input checked="" type="checkbox"/>
286763	WELL	PR	06/13/2007	GW	045-12729	STUBBS RWF 512-5	PR	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

286764	WELL	PR	06/13/2007	GW	045-12728	STUBBS RWF 311-5	PR	<input checked="" type="checkbox"/>
286765	WELL	PR	06/18/2008	GW	045-12727	STUBBS RWF 411-5	PR	<input checked="" type="checkbox"/>
286766	WELL	PR	06/13/2007	GW	045-12726	STUBBS RWF 21-5	PR	<input checked="" type="checkbox"/>
286767	WELL	PR	06/18/2008	GW	045-12725	STUBBS RWF 521-5	PR	<input checked="" type="checkbox"/>
286768	WELL	PR	06/18/2008	GW	045-12724	STUBBS RWF 511-5	PR	<input checked="" type="checkbox"/>
286769	WELL	PR	06/13/2007	GW	045-12723	STUBBS RWF 421-5	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1403-002		

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 16	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Emission Control Device	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment	Disconnected		
Corrective Action			Date:
Type: Ancillary equipment	# 4	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Plunger Lift	# 16	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

<b>Facilities:</b>	<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity
PRODUCED WATER	1	300 BBLS
Type	STEEL AST	
SE GPS		
S/AR	Comment:	
Corrective Action:		Corrective Date:

<u>Paint</u>
Condition
Other (Content)
Other (Capacity)
Other (Type)

<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

<b>Facilities:</b>	<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity
PRODUCED WATER	1	200 BBLS
Type	STEEL AST	
SE GPS		
S/AR	Comment:	
Corrective Action:		Corrective Date:

<u>Paint</u>
Condition
Other (Content)
Other (Capacity)
Other (Type)

<u>Berms</u>
--------------

Inspector Name: Murray, Richard

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Corrective Action					Corrective Date	
Comment						

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	39.470440,-107.915440

S/AR	SATISFACTORY	Comment:				
------	--------------	----------	--	--	--	--

Corrective Action:					Corrective Date:	
--------------------	--	--	--	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action					Corrective Date	
Comment						

**Venting:**

Yes/No	YES
Comment	Bradenhead valves open

**Flaring:**

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:			Correct Action Date:

**Predrill**

Location ID: 286769

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 284915 Type: WELL API Number: 045-12302 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 284917 Type: WELL API Number: 045-12301 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 286731 Type: WELL API Number: 045-12736 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Inspector Name: Murray, Richard

Facility ID:	286732	Type:	WELL	API Number:	045-12735	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286733	Type:	WELL	API Number:	045-12734	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286759	Type:	WELL	API Number:	045-12733	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286760	Type:	WELL	API Number:	045-12732	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286761	Type:	WELL	API Number:	045-12731	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286762	Type:	WELL	API Number:	045-12730	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286763	Type:	WELL	API Number:	045-12729	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286764	Type:	WELL	API Number:	045-12728	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286765	Type:	WELL	API Number:	045-12727	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286766	Type:	WELL	API Number:	045-12726	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286767	Type:	WELL	API Number:	045-12725	Status:	PR	Insp. Status:	PR
<div>Producing Well</div> <div>Comment: <span>Plunger lift</span></div>									
Facility ID:	286768	Type:	WELL	API Number:	045-12724	Status:	PR	Insp. Status:	PR

Inspector Name: Murray, Richard

**Producing Well**

Comment: **Plunger lift**

Facility ID: 286769 Type: WELL API Number: 045-12723 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): Y \_\_\_\_\_

Comment: **Disconnected**

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Inspector Name: Murray, Richard

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Ditches	Pass					
		Compaction	Pass			

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_



<b>Pits:</b> <input checked="checked" type="checkbox"/> NO SURFACE INDICATION OF PIT	
--	--