

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/13/2016

Document Number:

679900958

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>213380</u>	<u>324880</u>	<u>Welsh, Brian</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10324</u>
Name of Operator:	<u>NEWELL ENERGY LTD</u>
Address:	<u>PO BOX 830808</u>
City:	<u>SAN ANTONIO</u> State: <u>TX</u> Zip: <u>78283</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Trbovich, Laurence	719-388-1839	trbo@nrso.us	

Compliance Summary:

QtrQtr: SWNE Sec: 28 Twp: 20S Range: 49W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/13/2014	668603024	PR	PR	SATISFACTORY	I		No
02/27/2012	663900678	PR	PR	ACTION REQUIRED	F		No
07/27/2010	200264626	PR	PR	SATISFACTORY			No
10/01/2009	200220152	PR	PR	ACTION REQUIRED			Yes
06/01/2009	200211643	PR	PR	ACTION REQUIRED			Yes
02/06/2008	200126429	PR	SI	SATISFACTORY			No
06/27/2007	200113675	PR	PR	ACTION REQUIRED		Fail	Yes
11/17/2004	200064058	PR	PR	SATISFACTORY		Pass	No
06/23/2004	200058994	PR	PR	ACTION REQUIRED		Fail	Yes
03/17/2000	200005295	PR	PR	ACTION REQUIRED	I	Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213380	WELL	PR	07/01/2005	GW	061-06742	ARWOOD 1	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

--

Inspector Name: Welsh, Brian

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	Dirt road through pasture		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Lease sign mounted to fence at wellhead		
TANK LABELS/PLACARDS	SATISFACTORY	Sticker on separator and metal sign by tank		

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Metal panels around wellhead		

Equipment:

Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date: _____	
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date: _____	
Type: Plunger Lift	# 1	Satisfactory/Action Required: SATISFACTORY

Comment			
Corrective Action			Date:

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST	38.289620,-102.902310

S/AR	SATISFACTORY	Comment:		
------	--------------	----------	--	--

Corrective Action:			Corrective Date:		
--------------------	--	--	------------------	--	--

Paint

Condition				
-----------	--	--	--	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action			Corrective Date		
-------------------	--	--	-----------------	--	--

Comment				
---------	--	--	--	--

Venting:

Yes/No	NO			
--------	----	--	--	--

Comment				
---------	--	--	--	--

Flaring:

Type		Satisfactory/Action Required		
------	--	------------------------------	--	--

Comment:				
----------	--	--	--	--

Corrective Action:			Correct Action Date:		
--------------------	--	--	----------------------	--	--

Predrill

Location ID: 213380

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: SATISFACTORY **Comment:** No COAs

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 213380 Type: WELL API Number: 061-06742 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____
CA _____ CA Date _____

Guy line anchors marked? _____

CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: Welsh, Brian

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT