

Environmental Field Inspection Photos  
1/13/16  
Spill Location # 444493  
05-071-08843 Vallejo 44-5R



Figure 1 – Lease Sign



Figure 2 – Looking from well pad into ephemeral drainage off pad.





Figure 3 – Looking into ephemeral drainage off pad.



Figure 4 – Wellhead and pad.