

Interim Reclamation Inspection

1/13/2016

Operator: Atlas Resources

Location ID: 426964

API: 095-06389

Phillips County, CO

SESE Section 3 T8N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo sign at wellhead.



01.13.2016 12:05

Figure 2: Photo taken from north end of location, facing south. Photo shows project area.



Figure 3: Photo taken from the northwest end of location, facing south. Photo shows project and interim area. Photo shows portions of the interim area with sparse vegetation and exposed soil



Figure 4: Photo taken from the west end of location, facing east. Photo shows project and interim area. Photo shows portions of the interim area with sparse vegetation and exposed soil



Figure 5: Photo taken at wellhead. Photo shows erosion starting to occur from the project area.



Figure 6: Photo taken north end of location, facing west. Photo shows erosion starting to occur from the project area leaving location.



Figure 6: Photo taken from the northwest end of location, facing south. Photo shows project and interim area. Photo shows portions of the interim area with sparse vegetation and exposed soil



Figure 6: Photo taken south end of location, facing north. Photo shows project and interim area. Photo shows portions of the interim area with sparse vegetation and exposed soil.