



Photo#1: Overview of Location, looking East.



Photo#2 Slash Debris Piles.



Photo#3: Rock , pushed to edge of Location.





Photo#4: Pipe (Marker?) at edge of Creek.



Photo#5: Trash being stashed behind Boulders.





Photo#6: Google earth image of Juhan #1.