

FORM
5A

Rev
06/12

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400971096

Date Received:

01/14/2016

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66561
2. Name of Operator: OXY USA INC
3. Address: 760 HORIZON DR #101
City: GRAND JUNCTION State: CO Zip: 81506
4. Contact Name: Joan Proulx
Phone: (970) 263-3641
Fax: (970) 263-3694
Email: joan_proulx@oxy.com

5. API Number 05-077-08938-00
6. County: MESA
7. Well Name: MCDANIEL
Well Number: 2-1
8. Location: QtrQtr: NENE Section: 2 Township: 9S Range: 94W Meridian: 6
9. Field Name: BRUSH CREEK Field Code: 7562

Completed Interval

FORMATION: CORCORAN Status: PRODUCING Treatment Type:
Treatment Date: End Date: Date of First Production this formation:
Perforations Top: 8808 Bottom: 8891 No. Holes: 18 Hole size: 34/100
Provide a brief summary of the formation treatment: Open Hole: ☐
This formation is commingled with another formation: ☐ Yes ☒ No
Total fluid used in treatment (bbl): Max pressure during treatment (psi):
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):
Type of gas used in treatment: Min frac gradient (psi/ft):
Total acid used in treatment (bbl): Number of staged intervals:
Recycled water used in treatment (bbl): Flowback volume recovered (bbl):
Fresh water used in treatment (bbl): Disposition method for flowback:
Total proppant used (lbs): Rule 805 green completion techniques were utilized: ☐
Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:
Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:
Test Method: Casing PSI: Tubing PSI: Choke Size:
Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:
Tubing Size: 2 + 3/8 Tubing Setting Depth: 7360 Tbg setting date: 12/31/2015 Packer Depth:
Reason for Non-Production:
Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt
** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type: _____

Treatment Date: _____ End Date: _____ Date of First Production this formation: _____

Perforations Top: 6586 Bottom: 8154 No. Holes: 138 Hole size: 34/100

Provide a brief summary of the formation treatment: _____ Open Hole: ☐

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl): _____ Max pressure during treatment (psi): _____

Total gas used in treatment (mcf): _____ Fluid density at initial fracture (lbs/gal): _____

Type of gas used in treatment: _____ Min frac gradient (psi/ft): _____

Total acid used in treatment (bbl): _____ Number of staged intervals: _____

Recycled water used in treatment (bbl): _____ Flowback volume recovered (bbl): _____

Fresh water used in treatment (bbl): _____ Disposition method for flowback: _____

Total proppant used (lbs): _____ Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized: _____

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: _____ Hours: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____

Calculated 24 hour rate: _____ Bbl oil: _____ Mcf Gas: _____ Bbl H2O: _____ GOR: _____

Test Method: _____ Casing PSI: _____ Tubing PSI: _____ Choke Size: _____

Gas Disposition: _____ Gas Type: _____ Btu Gas: _____ API Gravity Oil: _____

Tubing Size: 2 + 3/8 Tubing Setting Depth: 7360 Tbg setting date: 12/31/2015 Packer Depth: _____

Reason for Non-Production: _____

Date formation Abandoned: _____ Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt _____

** Bridge Plug Depth: _____ ** Sacks cement on top: _____ ** Wireline and Cement Job Summary must be attached.

Comment:

Work occurred on the McDaniel 2-1 well to repair the tubing.

Estimate top of fish is 7498'

Tagged obstruction in fish with sandline on 12/31/2015 at 8244'

Estimated bottom of fish 8408'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 1/14/2016 Email joan_proulx@oxy.com

Attachment Check List

Att Doc Num	Name
400971096	FORM 5A SUBMITTED
400971105	WIRELINE JOB SUMMARY
400971106	WIRELINE JOB SUMMARY

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Operator reports trouble in clearing tubing obstruction.	1/20/2016 2:01:52 PM

Total: 1 comment(s)