

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2016

Document Number:

681900435

Overall Inspection:

SATISFACTORY w/ CMT
or AR

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>241534</u>	<u>335761</u>	<u>HELGELAND, GARY</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>68710</u>
Name of Operator:	<u>PETERSON ENERGY OPERATING INC</u>
Address:	<u>2154 W EISENHOWER BLVD</u>
City:	<u>LOVELAND</u> State: <u>CO</u> Zip: <u>80537</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Peterson, Andy	/8960	andy.peterson@petersonenergy.com	

Compliance Summary:

QtrQtr: SWSE Sec: 34 Twp: 1N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/14/2013	668700742	PA	PA	ACTION REQUIRED		Fail	No
08/30/2010	200270612	HR	PA	ACTION REQUIRED	F		Yes
03/18/2010	200238546	CA	PA	SATISFACTORY			No
03/17/2010	200238545	CA	PA	SATISFACTORY			No
03/16/2010	200238544	CA	PA	SATISFACTORY			No
03/16/2010	200238363	CA	PA	SATISFACTORY			No
04/11/2005	200069850	PR	PR	SATISFACTORY		Pass	No
07/08/2000	200007722	PR	PR	SATISFACTORY		Pass	No
08/07/1996	500164208	CO	PR				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
241534	WELL	PA	03/16/2010	OW	123-09323	BURKHARDT 2	PA	<input checked="" type="checkbox"/>
263558	WELL	PR	05/08/2002	GW	123-20919	SELTZER 34-34	PR	<input type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 241534

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 241534 Type: WELL API Number: 123-09323 Status: PA Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____
 Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass
 Debris removed Fail No disturbance /Location never built _____
 Access Roads Regraded Pass Contoured Pass Culverts removed _____
 Gravel removed Pass
 Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: **ELECTRICAL EQUIPMENT REMAINS ON LOCATION.**

Corrective Action: **REMOVE ELECTRICAL EQUIPMENT.** Date **03/22/2016**

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681900436	ELECTRICAL EQUIPMENT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3767763