

EXCAVATION FIELD FORM

SITE NAME / API #: Bayswater / Walton 17-25 WellheadDATE: 12/18/15 WEATHER: 30's SunnySITE DIRECTIONS: CR 78 / 23 E 1.0 S mls

WO#

LEGALS AND LAT/LONG:

DIST./DIR. TO NEAREST WATER WELL (ft.):

SOIL TYPES:

DEPTH TO GROUNDWATER:

LAND USE: AgricultureLINER PRESENT: H

SURFACE WATER:

LIVESTOCK PRESENT: No

OCCUPIED BUILDING:

CLIENT PERSONNEL:

HISTORICAL/RECENT RELEASE:

SUMP REPLACEMENT/CLOSURE:

TASMAN PERSONNEL: Bruck N

Date	Soil Sample ID	Time	PID ppm	Stain?	Odor?	Lab?
------	----------------	------	---------	--------	-------	------

WHAT SPILLED:

AMOUNT SPILLED:

CAUSE OF SPILL:

12/18/15	SS01@3"	1305	1434	N	Y	Y
----------	---------	------	------	---	---	---

	SS02@3"	1305	902	N	Y	Y
--	---------	------	-----	---	---	---

1/22/16	SS03@18"	1350	255	N	N	Y
---------	----------	------	-----	---	---	---

	SS04@18"	1355	355	N	N	Y
--	----------	------	-----	---	---	---

HOW WAS IT FOUND:

HOW WAS IT STOPPED/CONTAINED:

HOW WAS IT RECOVERED:

Soil Disposal Facility:

Soil Loads Removed

Date

Number

Total Yards Removed:

GW Disposal Facility:

Date

BBL'S Out

TOTAL REMOVED

GROUNDWATER:

N/A

Date	Groundwater Sample ID	Time	Sheen?	Color	Odor?	Lab?
------	-----------------------	------	--------	-------	-------	------

Bagswater

Walton 17-25 Wellhead

12/14/15

