

COMMENTS

An evaluation considered all water sources within a 1/2 mile radius of well pad RU 13-6 (Location ID 324106). Two water sources were located within that radius, but were deemed unsuitable. The water sources are monitoring wells lack dedicated pumps and are either dry or contain very little water. Please see attached document for details. This sundry applies to API numbers:

- 05-045-22592
- 05-045-22593
- 05-045-22594
- 05-045-22595
- 05-045-22596
- 05-045-22597
- 05-045-22598
- 05-045-22599
- 05-045-22600
- 05-045-22601
- 05-045-22602
- 05-045-22603
- 05-045-22604
- 05-045-22605
- 05-045-22606
- 05-045-22607
- 05-045-22608
- 05-045-22609
- 05-045-22610
- 05-045-22611
- 05-045-22612

Operator Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jessie Pahler
 Title: Project Scientist Email: jpahler@westernwaterandland.com Date: _____

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type	Description

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)

Attachment Check List

Att Doc Num	Name
400977927	WATER ANALYSIS

Total Attach: 1 Files