

CLOUGH W F
API 05-045-05189
LW Clough 1-B



Access Road looking west. I-70 on left side behind fence.



Wellhead with separator, No sign

CLOUGH W F
API 05-045-05189
LW Clough 1-B



Wellhead Shut in, New Ball valve and Needle valve



Access road looking east, I-70 on right side behind fence