



Photo#1: Looking from North end of Location over Interim Reclamation & Approximate site of P&A 045-06178.



Photo#2: View South of location from North Interim Reclamation , over site of P&A 045-06178.

January 24, 2016

Inspection Photos Barrett 045-06178



Photo#3: View SE of Location .





Photo#4: View West over North Interim Reclamation and site of P&A 045-06178.