

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2016

Document Number:

675202462

Overall Inspection:

SATISFACTORY w/ CMT
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334516	334516	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757 #110City: HOUSTON State: TX Zip: 77227-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		chris_clark@oxy.com	

Compliance Summary:QtrQtr: NWSE Sec: 36 Twp: 9S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/27/2015	675201115			ACTION REQUIRED			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
284757	WELL	PR	09/18/2007	GW	077-09069	LARAMIE LAND & CATTLE CO 36-7	PR	<input checked="" type="checkbox"/>
284758	WELL	PR	09/18/2009	GW	077-09067	LARAMIE LAND & CATTLE CO 36-8A	PR	<input checked="" type="checkbox"/>
284759	WELL	PR	05/01/2010	GW	077-09068	LARAMIE LAND & CATTLE CO 36-8	PR	<input checked="" type="checkbox"/>
284761	WELL	PR	09/15/2014	GW	077-09066	LARAMIE LAND & CATTLE CO. 36-9	PR	<input checked="" type="checkbox"/>
284762	WELL	PR	08/18/2010	GW	077-09062	LARAMIE LAND & CATTLE CO 36-10A	PR	<input checked="" type="checkbox"/>
284764	WELL	PR	07/09/2007	GW	077-09065	LARAMIE LAND & CATTLE 36-14A	PR	<input checked="" type="checkbox"/>
284765	WELL	PR	02/01/2015	GW	077-09064	LARAMIE LAND & CATTLE CO 36-10	PR	<input checked="" type="checkbox"/>
284767	WELL	PR	09/30/2009	GW	077-09063	LARAMIE LAND&CATTLE CO. 36-14	PR	<input checked="" type="checkbox"/>
288275	WELL	PR	09/26/2007	GW	077-09213	LARAMIE LAND&CATTLE,CO 36-11	PR	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

288276	WELL	PR	03/21/2011	GW	077-09212	LARAMIE LAND&CATTLE,CO 36- 9A	PR	<input checked="" type="checkbox"/>
288277	WELL	PR	02/08/2008	GW	077-09211	LARAMIE LAND&CATTLE,CO.FE D 31-12	PR	<input checked="" type="checkbox"/>
288278	WELL	PR	08/18/2010	GW	077-09210	LARAMIE LAND&CATTLE,CO. 36- 7A	PR	<input checked="" type="checkbox"/>
288279	WELL	PR	06/24/2008	GW	077-09209	LARAMIE LAND & CATTLE,CO 36-11A	PR	<input checked="" type="checkbox"/>
288280	WELL	PR	01/01/2010	GW	077-09208	LARAMIE LAND&CATTLE,CO. 36- 15	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	ACTION REQUIRED	Three wells missing signs (36-11, 36-7, 36-9A) See attached photos.	Install sign to comply with rule 210.	02/27/2016

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: 970-248-0497

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date:

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST	,
S/AR	SATISFACTORY	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 334516

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 284757 Type: WELL API Number: 077-09069 Status: PR Insp. Status: PR

Facility ID: 284758 Type: WELL API Number: 077-09067 Status: PR Insp. Status: PR

Facility ID: 284759 Type: WELL API Number: 077-09068 Status: PR Insp. Status: PR

Facility ID: 284761 Type: WELL API Number: 077-09066 Status: PR Insp. Status: PR

Facility ID: 284762 Type: WELL API Number: 077-09062 Status: PR Insp. Status: PR

Facility ID: 284764 Type: WELL API Number: 077-09065 Status: PR Insp. Status: PR

Inspector Name: CONKLIN, CURTIS

Facility ID:	284765	Type:	WELL	API Number:	077-09064	Status:	PR	Insp. Status:	PR
Facility ID:	284767	Type:	WELL	API Number:	077-09063	Status:	PR	Insp. Status:	PR
Facility ID:	288275	Type:	WELL	API Number:	077-09213	Status:	PR	Insp. Status:	PR
Facility ID:	288276	Type:	WELL	API Number:	077-09212	Status:	PR	Insp. Status:	PR
Facility ID:	288277	Type:	WELL	API Number:	077-09211	Status:	PR	Insp. Status:	PR
Facility ID:	288278	Type:	WELL	API Number:	077-09210	Status:	PR	Insp. Status:	PR
Facility ID:	288279	Type:	WELL	API Number:	077-09209	Status:	PR	Insp. Status:	PR
Facility ID:	288280	Type:	WELL	API Number:	077-09208	Status:	PR	Insp. Status:	PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment:
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐

Inspector Name: CONKLIN, CURTIS

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: Could not do complete stormwater inspection due to snow cover.

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675202463	36-11	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3769545
675202464	36-7	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3769546
675202465	36-9A	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3769547