

Interim Reclamation Inspection

1/25/2016

Operator: Atlas Resources LLC

Location ID: 314074

API: 095-06165

Phillips County, CO

NWSW Section 33 T9N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken at well head, facing east. Photo of sign and well.



Figure 2: Photo taken east of location, facing west. Photo shows portions of the interim area with sparse vegetation and exposed soil.



Figure 3: Photo taken north of location, facing south. Photo shows portions of the interim area with sparse vegetation and exposed soil (indicated by arrow).



Figure 4: Photo taken from the northwest end of location, facing southeast. Photo shows portions of the interim area with sparse vegetation and exposed soil (indicated by arrow).



Figure 5: Photo taken northwest of location, facing east. Photo shows portions of the interim area with sparse vegetation and exposed soil (indicated by arrow).



Figure 6: Photo taken west of location, facing east. Photo shows portions of the interim area with sparse vegetation and exposed soil (indicated by arrow).




Figure 7: Aerial image of wells 095-06165 and 095-06399. Blue arrows indicates portions of interim area with sparse cover and bare soil. Red arrow indicates pipeline between wells with subsidence concerns.