

Interim Reclamation Inspection

1/25/2016

Operator: Atlas Resources LLC

Location ID: 424283

API: 095-06319

Phillips County, CO

SWSW Section 28 T9N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo taken at well head. Photo of sign and well. Note weedy vegetation among equipment.



Figure 2: Photo taken east of well, facing west. Photo shows undesirable weedy vegetation becoming abundant within project area.



Figure 3: Photo taken north of location, facing south. Photo shows area of sparse vegetation in interim area.



Figure 4: Photo taken west of location, facing east. Photo shows interim and project areas.



Figure 5: Photo taken east of location, facing west. Photo shows Photo undesirable weedy vegetation becoming abundant within project area.



Figure 6: Photo taken southeast of location, facing northwest. Photo shows interim and project areas.