

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2016

Document Number:

681900488

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 276444 | 332926 | HELGELAND, GARY | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|-----------------|
| Reddy, Luke | | luke.reddy@anadarko.com | All Inspections |
| , | | COGCCinspections@anadarko.com | All Inspections |

Compliance Summary:QtrQtr: NWNW Sec: 28 Twp: 2N Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 03/24/2011 | 200305259 | PR | PR | SATISFACTORY | | | No |
| 01/26/2007 | 200104956 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|-------------------------------------|
| 241391 | WELL | PR | 06/26/1977 | OW | 123-09180 | CLEVELAND 8 | PR | <input type="checkbox"/> |
| 276444 | WELL | PR | 06/08/2005 | GW | 123-22773 | HEISMAN V 28-4 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date:

Comment:

Corrective Action:

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|----------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Pipe and rod fencing | | |

| Equipment: | | | | |
|--------------------|---|--|--|----------------|
| Type: Plunger Lift | # 3 | Satisfactory/Action Required: <u> </u> | | |
| Comment | Refer to inspection # 68900487 for further battery discription. | | | |
| Corrective Action | | | | Date: <u> </u> |

| Venting: | |
|-----------------|----|
| Yes/No | NO |
| Comment | |

| Flaring: | | | |
|--------------------|------------------------------|----------------------|--|
| Type | Satisfactory/Action Required | | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 276444

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 276444 Type: WELL API Number: 123-22773 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: HELGELAND, GARY

| | | |
|---|--|----------------------|
| Comment: <input style="width: 700px;" type="text"/> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |
| <u>Water Well:</u> | | |
| | | Lat _____ Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |
| <u>Field Parameters:</u> | | |
| <input style="width: 300px;" type="text"/> | | |
| Sample Location: <input style="width: 400px;" type="text"/> | | |
| Emission Control Burner (ECB): Y _____ | | |
| Comment: _____ | | |
| Pilot: ON _____ | Wildlife Protection Devices (fired vessels): YES _____ | |

Reclamation - Storm Water - Pit

Interim Reclamation:

| | |
|--|---|
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <input style="width: 750px;" type="text"/> | |
| 1003a. Waste and Debris removed? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Unused or unneeded equipment onsite? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Pit, cellars, rat holes and other bores closed? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Guy line anchors marked? _____ | |
| CM _____ | |
| CA _____ | CA Date _____ |
| 1003b. Area no longer in use? _____ | Production areas stabilized ? <u>Pass</u> |
| 1003c. Compacted areas have been cross ripped? _____ | |
| 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ | |
| Cuttings management: _____ | |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ | |
| Production areas have been stabilized? _____ | Segregated soils have been replaced? _____ |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |
| Top soil replaced _____ | Recontoured _____ Perennial forage re-established _____ |

Inspector Name: HELGELAND, GARY

Non-Cropland

Top soil replaced Pass

Recontoured Pass

80% Revegetation In

1003 f. Weeds Noxious weeds? _____

Comment: Location snow covered.

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT