

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/29/2016
Document Number:
673712484
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>253781</u>	<u>303909</u>	<u>Sherman, Susan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10112</u>
Name of Operator:	<u>FOUNDATION ENERGY MANAGEMENT LLC</u>
Address:	<u>16000 DALLAS PARKWAY #875</u>
City:	<u>DALLAS</u> State: <u>TX</u> Zip: <u>75248-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Foundation Energy		regulatory@foundationenergy.com	

Compliance Summary:

QtrQtr:	<u>NWSE</u>	Sec:	<u>32</u>	Twp:	<u>1N</u>	Range:	<u>45W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/02/2011	200299304	PR	PR	SATISFACTORY	I		No
12/05/1995	500180333	PR	PR			Pass	No
12/28/1994	500180332	PR	WO				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
101005	PIT	CL	10/09/2014		-	STULTS 33-32	CL <input type="checkbox"/>
253781	WELL	PR	07/20/2008	GW	125-07659	STULTS 33-32	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access		through field		

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	lease sign @ CR X		
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	steel panels		
OTHER	SATISFACTORY	hog wire panels around meter shed		
PUMP JACK	SATISFACTORY	steel panels		

Equipment:				
Type: Vertical Separator	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	in meter shed			
Corrective Action				Date:
Type: Prime Mover	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	electric motor			
Corrective Action				Date:
Type: Pump Jack	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	concrete pad, Stuffing box leak-not on ground (see attached photo)			
Corrective Action				Date:
Type: Ancillary equipment	# 4	Satisfactory/Action Required:	SATISFACTORY	
Comment	electric panel and chemical container at wellhead, solar panel and radio telemetry at meter shed			
Corrective Action				Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	shed, GPS 40/00702, -102.41649			

Corrective Action	Date:
-------------------	-------

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required
Comment:		
Corrective Action:		Correct Action Date:

Predrill

Location ID: 253781

Site Preparation:
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:
S/AR: SATISFACTORY **Comment:** No COAs.

CA: _____ **Date:** _____

Wildlife BMPs:
S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:
 Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:
 Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 253781 Type: WELL API Number: 125-07659 Status: PR Insp. Status: PR

Producing Well

Comment: PR. Nov 2015 reported to COGCC database.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: corn stubble, center pivot
1003a. Waste and Debris removed? Pass
CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass
CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass
CM _____
CA _____ CA Date _____
Guy line anchors marked? _____
CM _____
CA _____ CA Date _____
1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Inspector Name: Sherman, Susan

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	SI	Pass	
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673712507	Foundation Stults 33-32	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3772565