

## Abandoned Location Inspection



**Photo 1.** Photo taken of PR well 001-08696, confirming the AL status of 001-09557. It appears 001-09557 was never built at location. This is a well release on an active location.

## Abandoned Location Inspection



**Photo 2.** Photo taken of PR well 001-08696, confirming the AL status of 001-09557. It appears 001-09557 was never built at location. This is a well release on an active location.