

Abandoned Location Inspection



Photo 1. Photo taken of PR well 001-09387, confirming the AL status of 001-09559. It appears 001-09559 was never built at location. This is a well release on an active location.

Abandoned Location Inspection



Photo 2. Photo taken of PR well 001-09387, confirming the AL status of 001-09559. It appears 001-09559 was never built at location. This is a well release on an active location.