

Abandoned Location Inspection



Photo 1. Photo taken of PR well 013-06566, confirming the AL status of 013-06655, 013-06656, and 013-06657. It appears 013-06655, 013-06656, and 013-06657 were never built at location. This is a well release on an active location.

Abandoned Location Inspection



Photo 2. Photo taken of PR well 013-06566, confirming the AL status of 013-06655, 013-06656, and 013-06657. It appears 013-06655, 013-06656, and 013-06657 were never built at location. This is a well release on an active location.