

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2016

Document Number:

674003366

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 246759 | 327358 | Carlile, Craig | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|-------------------------------|-----------------|
| , Reddy | | luke.reddy@anadarko.com | |
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |
| Avant, Paul | (720) 929-6457 | Paul.Avant@Anadarko.com | All Inspections |

Compliance Summary:QtrQtr: NWNE Sec: 33 Twp: 3N Range: 66W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 11/26/2013 | 674000042 | PR | PR | SATISFACTORY | | | No |
| 01/13/2006 | 200086914 | PR | PR | SATISFACTORY | | Pass | No |
| 01/12/2006 | 200086912 | PR | PR | SATISFACTORY | | Pass | No |
| 01/06/2000 | 200002560 | PR | PR | SATISFACTORY | | Pass | No |
| 11/05/1996 | 500171236 | PR | PR | | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 246759 | WELL | PR | 04/11/2003 | GW | 123-14556 | SARCHET UPRR 31-33 2A | PR |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| | | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Fencing/:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Equipment:

| | | | |
|-----------------------------------|-----|-------------------------------|--------------|
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Horizontal Heated Separator | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |

Facilities:☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|---|----------|--------------|------------------|
| PRODUCED WATER | 1 | <50 BBLS | PBV CONCRETE | , |
| S/AR | | Comment: | | |
| Corrective Action: | | | | Corrective Date: |

Paint

Condition _____

Other (Content) _____

Inspector Name: Carlile, Craig

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|-----------------------------|
| Comment | Shared with crude oil tank. |
|---------|-----------------------------|

Facilities: ☐ New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|-----------|---|----------|-----------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.188290,-104.782100 |

| | | | |
|------|--|----------|--|
| S/AR | | Comment: | |
|------|--|----------|--|

| | | | |
|--------------------|--|------------------|--|
| Corrective Action: | | Corrective Date: | |
|--------------------|--|------------------|--|

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Venting:

| | |
|--------|--|
| Yes/No | |
|--------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Flaring:

| | | | |
|------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
|------|--|------------------------------|--|

Comment: _____

| | | | |
|--------------------|--|----------------------|--|
| Corrective Action: | | Correct Action Date: | |
|--------------------|--|----------------------|--|

Predrill

Location ID: 246759

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat

Long

Inspector Name: Carlile, Craig

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Inspector Name: Carlile, Craig

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Follow up inspection. Previous weed issue has been addressed. | carlilec | 02/09/2016 |