

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/05/2016
Document Number:
682600070
Overall Inspection:
ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	444661	314203	Kosola, Jason	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 8005
Name of Operator: BERRY ENERGY INC*WALTER
Address: 1717 WASHINGTON AVE
City: GOLDEN State: CO Zip: 80401-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Dennis, Penny	303-279-0190/66190	berryenergy@comcast.net	
Smith, Ed		edwardh.smith@state.co.us	
Axelson, John		john.axelson@state.co.us	
Cruson, Michael	(303) 279-0190	mcruson@berryenergyinc.com	All Inspections

Compliance Summary:

QtrQtr: _____ Sec: _____ Twp: _____ Range: _____

Inspector Comment:

Reclamation Inspector issued inspection 673503100 on 1/28/16 documenting what appears to be an ongoing release of lube oil from the compressor station. This is a follow up inspection. Coordinates for compressor station: 37.960297, -102.501978 Any corrective actions from previous inspections that have not been addressed are still applicable.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
228001	WELL	PA	12/28/2010	GW	099-06328	NEU 1-17	PA	<input type="checkbox"/>
444661	GAS COMPRESSOR	AC	02/01/2016		-	NEU Compressor	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	ACTION REQUIRED	55 gallon barrels stored on location. Some of the barrels are not labeled. Operator informed of issue via phone on 2/8/16.	Install sign to comply with rule 210.	03/10/2016

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	Uncontrolled weeds and trash on location. Operator informed of trash issue via phone call on 2/8/16	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	02/19/2016

Spills:				
Type	Area	Volume	Corrective action	CA Date
Lube Oil		<= 1 bbl	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact CDPHE staff to make proper notification for cleanup of Non-E&P waste.	02/11/2016

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type: Compressor	# 1	Satisfactory/Action Required: ACTION REQUIRED		
Comment	Compressor draining into bucket on ground. No secondary containment present. Bucket appears to have been overflowing. Operator informed of leak via phone on 2/8/16			
Corrective Action	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.		Date: 2/10/2016	

Venting:	
Yes/No	
Comment	

Flaring:	
Type	Satisfactory/Action Required

Comment:		
Corrective Action:		Correct Action Date:

Predrill

Location ID: 444661

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 444661 Type: GAS API Number: - Status: AC Insp. Status: AC

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Kosola, Jason

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Waste Management:					
Type	Management	Condition	Comment	GPS (Lat)	(Long)

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
Comment: _____

1003a. Waste and Debris removed? _____
CM _____
CA _____ CA Date _____

Unused or unneeded equipment onsite? _____
CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____
CM _____
CA _____ CA Date _____

Guy line anchors marked? _____
CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: Kosola, Jason

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: **ACTION REQUIRED** Corrective Date: **02/11/2016**

Comment: **Failure to comply with Rule 1002.f.A. and 1002.f.B. Operator informed of issue via phone call on 2/8/16.**

CA: **Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.**

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Operator has stored Non Exploration and Production waste improperly and waste has spilled onto soils on location. COGCC is referring cleanup of Non-E&P waste to the Colorado Department of Public Health and Environment (CDPHE). Operator shall contact CDPHE to make proper notifications.	kosolaj	02/09/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600071	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3779758