



Photo#1: Overview of Location.



Photo#2: Evidence of old flow lines.



Photo#3: Evidence of old flow lines.



Photo#4: Evidence of old flow lines, close up of installation.



Photo#5: Evidence of old flow lines, Duct Tape covers disintegrating .