

# Interim Reclamation Inspection

2/9/2016

Operator: Whiting Oil and Gas

Location ID: 430061

Weld County, CO

SESE Section 14 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



02.09.2016 11:14

**Figure 1:** Photo of well head and sign.





**Figure 2:** Photo taken from northeast end of location, facing south. Photo of interim and project areas.





**Figure 3:** Photo taken from northeast end of location, facing west. Photo of interim and project areas.





**Figure 4:** Photo taken from north end of location, facing west. Photo of vegetation on interim area.





02.09.2016 11:18

**Figure 5:** Photo taken from northern end of location, facing south. Photo of interim and project areas.





**Figure 6:** Photo taken from northwest end of location, facing east. Photo of interim and project areas.





**Figure 7:** Photo taken from northwest end of location, facing west. Photo of interim, project areas and stormwater control berm.





**Figure 8:** Photo taken from west end of location, facing west. Photo of stormwater control berm.





02.09.2016 11:20

**Figure 9:** Photo taken from western end of location, facing south. Photo of interim, project areas and stormwater control berm.






**Figure 10:** Photo taken from southwest end of location, facing north. Photo shows interim and project area, and stormwater berm.





**Figure 11:** Photo taken from southwest end of location, facing east. Photo of interim and project areas.





02.09.2016 11:22

**Figure 12:** Photo taken from southern end of location, facing north. Photo of vegetation on slope of interim area.





**Figure 13:** Photo taken from northern end of location, facing east. Photo shows vegetation on interim area.





**Figure 14:** Photo taken from the southeast end of location, facing north. Photo of interim and project areas.





**Figure 15:** Photo taken from the southeast end of location, facing west. Photo of interim and project areas.