

**FORM
INSP**
Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/09/2016
Document Number:
674702372
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>324202</u> | <u>324202</u> | <u>LONGWORTH, MIKE</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|--|
| OGCC Operator Number: | <u>10456</u> |
| Name of Operator: | <u>CAERUS PICEANCE LLC</u> |
| Address: | <u>600 17TH STREET #1600N</u> |
| City: | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|--------------|
| Janicek, Jake | | JJanicek@caerusoilandgas.com | |
| Elsener, Garrett | | garrett@caerusoilandgas.com | |
| McKee, Michael | | MMckee@caerusoilandgas.com | EHS Engineer |

Compliance Summary:

| | | | | | | | |
|---------|-------------|------|-----------|------|-----------|--------|------------|
| QtrQtr: | <u>NWSW</u> | Sec: | <u>25</u> | Twp: | <u>6S</u> | Range: | <u>97W</u> |
|---------|-------------|------|-----------|------|-----------|--------|------------|

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 05/12/2015 | 674701405 | | | SATISFACTORY | | | No |
| 11/19/2014 | 674700612 | | | SATISFACTORY | | | No |
| 05/13/2014 | 663903183 | | | SATISFACTORY | | | No |
| 05/08/2013 | 663800978 | | | ACTION REQUIRED | I | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|-----------|---------------------|--|
| 264433 | WELL | PR | 01/23/2014 | GW | 045-08216 | PUCKETT 216-25 | PR <input checked="" type="checkbox"/> |
| 279646 | PIT | CL | 01/20/2009 | | - | PUCKETT 216-25 | CL <input type="checkbox"/> |
| 443261 | SPILL OR RELEASE | CL | 09/18/2015 | | - | SPILL/RELEASE POINT | CL <input type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|------------------------------------|-------------------|------|
| Main | SATISFACTORY | Snow packed road starting to melt. | | |
| Access | SATISFACTORY | Snow packed road starting to melt. | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------------------|------------------------------|---------|-------------------|---------|
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: **866-580-9382**

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------|------------------------------|---------|-------------------|---------|
| SEPARATOR | SATISFACTORY | | | |
| TANK BATTERY | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Equipment:

| | | | |
|-----------------------------------|-------|-------------------------------|--------------|
| Type: Horizontal Heated Separator | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | Date: | | |
| Type: Bird Protectors | # 1 | Satisfactory/Action Required: | SATISFACTORY |

| | | |
|--------------------|-----|--|
| Comment | | |
| Corrective Action | | Date: |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: SATISFACTORY |
| Comment | | |
| Corrective Action | | Date: |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|----------|-----------|------------------|
| CONDENSATE | 1 | 400 BBLS | STEEL AST | , |
| S/AR | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|----------|-----------|------------------|
| METHANOL | 1 | <50 BBLS | STEEL AST | , |
| S/AR | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) 500 gallons

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | |
|------|--|------------------------------|
| Type | | Satisfactory/Action Required |
|------|--|------------------------------|

| | | | |
|--------------------|--|----------------------|--|
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 324202

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 264433 Type: WELL API Number: 045-08216 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____
 1003 f. Weeds Noxious weeds? _____
 Comment: _____
 Overall Interim Reclamation

Final Reclamation/ Abandoned Location:
 Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
 Final Land Use: _____
 Reminder: _____
 Comment: _____
 Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: SATISFACTOR
 Y
 Corrective Date: _____
 Comment: Limited inspection due to snow cover.
 CA: _____

Pits: NO SURFACE INDICATION OF PIT

| Permit: | Facility ID | Permit Num | Expiration Date |
|---------|-------------|------------|-----------------|
| | 279646 | 1433089 | |
| | 279646 | 1433089 | |