

**FORM  
INSP**

Rev  
05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/11/2016

Document Number:

681900621

Overall Inspection:

SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	239735	311278	HELGELAND, GARY	2A Doc Num:	

**Operator Information:**

OGCC Operator Number:	<u>46290</u>
Name of Operator:	<u>K P KAUFFMAN COMPANY INC</u>
Address:	<u>1675 BROADWAY, STE 2800</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

**Compliance Summary:**

QtrQtr: NENE Sec: 30 Twp: 2N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/01/2015	670901019	SI	SI	SATISFACTORY			No
09/10/2013	668300763	SI	SI	ACTION REQUIRED	P		No
02/04/2008	200125786	PR	PR	ACTION REQUIRED			
11/11/1999	500161359	PR	PR				
03/26/1998	500161358	PR	PR			Pass	No
06/25/1997	500161357	PR	PR			Fail	No
11/02/1995	500161356	PR	PR			Pass	No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
239735	WELL	SI	05/11/2009	OW	123-07523	TOM L. RUSSELL 1	SI	<input checked="" type="checkbox"/>
257460	WELL	PR	06/26/2010	GW	123-19978	HSR-RUSSELL 1-30A	PR	<input type="checkbox"/>
424724	WELL	PR	09/07/2012	OW	123-34151	OVERLOOK 21-30	PR	<input type="checkbox"/>
424727	WELL	PR	09/13/2012	OW	123-34153	OVERLOOK 7-30	PR	<input type="checkbox"/>
424731	WELL	PR	09/07/2012	OW	123-34155	OVERLOOK 8-30	PR	<input type="checkbox"/>
424732	WELL	PR	09/14/2012	OW	123-34156	OVERLOOK 2-30	PR	<input type="checkbox"/>

424735	WELL	PR	09/07/2012	OW	123-34158	OVERLOOK 28-30	PR	<input type="checkbox"/>
424737	WELL	PR	09/05/2012	OW	123-34159	OVERLOOK 27-30	PR	<input type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY	Chain link		
WELLHEAD	SATISFACTORY			

**Equipment:**

Type: Horizontal Heated Separator	# 2	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date: _____	
Type: Pump Jack	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		

Corrective Action		Date:
Type: Bird Protectors	# 2	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	40.112730,-104.924010
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

**Venting:**

Yes/No	NO
Comment	

**Flaring:**

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:		Correct Action Date:

**Predrill**

Location ID: 239735

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 239735 Type: WELL API Number: 123-07523 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: SATISFACTORY CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead is plumed to surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
Land Use: IRRIGATED  
Comment: \_\_\_\_\_  
1003a. Waste and Debris removed? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? Pass  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established In

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: Location snow covered.

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RESIDENTIAL

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location

Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

S/A/V: SATISFACTOR  
Y

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681900621	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3782058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3782058</a>