

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2016

Document Number:

666801918

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	260064	334566	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:QtrQtr: NWNE Sec: 9 Twp: 7S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/09/2013	670200829	PR	SI	SATISFACTORY			No
12/02/2010	200285476	PR	SI	SATISFACTORY			No
05/12/2006	200091757	PR	PR	SATISFACTORY	I	Pass	No
05/11/2006	200091755	PR	PR	SATISFACTORY	I	Pass	No
12/20/2003	200053425	PR	PR	SATISFACTORY	I	Pass	No
05/12/2003	200051075	CO	PR	SATISFACTORY	I	Pass	No
10/23/2002	200039195	CO	PR	ACTION REQUIRED		Fail	No
09/10/2002	200039201	CO	PR	SATISFACTORY		Pass	No
09/09/2002	200039202	CO	PR	SATISFACTORY		Pass	No
08/22/2002	200038697	DG	PR	SATISFACTORY		Pass	No
05/31/2002	200028428	CO	PR	SATISFACTORY		Fail	No
05/12/2002	200039219	CO	PR	SATISFACTORY		Pass	No
05/11/2002	200039218	CO	PR	SATISFACTORY		Pass	No
01/23/2002	200024659	BH	WO	SATISFACTORY		Pass	No
11/07/2001	200023733	CO	PR	SATISFACTORY		Pass	No
07/25/2001	200021691	DG	DG	SATISFACTORY		Pass	No
07/05/2001	200021191	CO	ND	ACTION REQUIRED		Fail	Yes
06/12/2001	200020472	DG	ND	SATISFACTORY		Pass	No

Inspector Comment:

Inspection is for wells with the status of Abandoned location

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
260064	WELL	TA	11/12/2013	GW	045-07812	GRASS MESA RANCH 4-16 (B9 WEST)	TA	<input type="checkbox"/>
260067	WELL	AL	07/09/2002	LO	045-07815	GRASS MESA RANCH 9-3 (B9 WEST)	AL	<input checked="" type="checkbox"/>
260068	WELL	AL	07/09/2002	LO	045-07816	GRASS MESA RANCH 4-15 (B9 WEST)	AL	<input checked="" type="checkbox"/>
260069	WELL	PR	06/04/2002	GW	045-07817	GRASS MESA RANCH 9-2 (B9 WEST)	PR	<input type="checkbox"/>
260070	WELL	AL	03/06/2002	GW	045-07818	GRASS MESA RANCH 4-14 (B9 WEST)	AL	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:

Inspector Name: Murray, Richard

Comment	
Corrective Action	Date:

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 260064

Site Preparation:

Lease Road Adeq.: Pads: Soil Stockpile:

S/AR:

Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/AR: **Comment:**

CA: **Date:**

Wildlife BMPs:

S/AR: **Comment:**

CA: **Date:**

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address: Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Inspector Name: Murray, Richard

Facility ID: 260067	Type: WELL	API Number: 045-07815	Status: AL	Insp. Status: AL
Facility ID: 260068	Type: WELL	API Number: 045-07816	Status: AL	Insp. Status: AL
Facility ID: 260070	Type: WELL	API Number: 045-07818	Status: AL	Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

Inspector Name: Murray, Richard

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **No visual sign of wells, Encana has producing wells on location**

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location ☒ Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

Inspector Name: Murray, Richard

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666801918	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3782568
666801923	encana	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3782565