

## Abandoned Location Inspection



**Photo 1.** Photo taken of PR well 123-25067, confirming the AL status of 123-27127. It appears 123-27127 was never built at location. This is a well release on an active location.

## Abandoned Location Inspection



**Photo 2.** Photo taken of PR well 123-27128, confirming the AL status of 123-27127. It appears 123-27127 was never built at location. This is a well release on an active location.