

Interim Reclamation Inspection

2/17/2016

Operator: Atlas Resources

Location ID: 425242

API: 095-06352

Phillips County, CO

NWNE Section 6 T8N R43W

Aaron Trujillo
Reclamation Specialist
COGCC



02.17.2016 13:37

Figure 1: Photo of sign at well.



Figure 2: Photo taken from access road, north of location facing south. Photo shows water pooling in access road and vehicle rutting in road.



Figure 3: Photo taken from access road, north of location. Photo shows erosion patterns leading off access road.



Figure 4: Photo taken from the northeast corner of location, facing south. Photo shows vegetation on interim area, and project area.



Figure 5: Photo taken from the southeast corner of location, facing north. Photo shows vegetation on interim area, and project area. Note large area on interim not uniformly vegetated.



Figure 6: Photo taken from the southeast corner of location, facing west. Photo shows vegetation on interim area, and project area.



Figure 7: Photo taken from the southeast corner of location, facing north. Photo portions of the interim area not uniformly vegetated.



Figure 8: Photo taken from the southeast corner of location, facing east. Photo shows vegetation on interim area, and project area.



Figure 9: Photo taken from the southwest corner of location, facing north. Photo shows vegetation on interim area, and project area.



Figure 10: Photo taken from the northwest corner of location, facing north. Photo shows vegetation on interim area, and project area.



Figure 11: Photo taken from the northwest corner of location, facing west. Photo shows vegetation on interim area, and project area.



Figure 12: Photo taken the northwest end of project area, facing southeast. Photo of vehicle rutting on location.



Figure 13: Photo taken the northwest end of project area, facing northwest. Photo shows subsidence occurring along pipeline.



Figure 14: Photo taken northwest of project area, facing northwest. Photo shows subsidence occurring along pipeline.



Figure 15: Photo taken northwest of project area, facing northwest. Photo shows subsidence occurring along pipeline.



02.17.2016 13:46

Figure 16: Photo taken county road 38, northwest of location, facing southeast. Photo shows subsidence occurring along pipeline from location.