



## LEASE INSPECTION FORM

Operator W.C. Hughes Date 5-25-89  
 Lease Name & No. Fassler Field Sundown  
 Tank Battery No. 2 N 53 A 34 County Washington  
 Location N 1/4 34-2N-53W  
 Legal Description

Type of Inspection \_\_\_\_\_  
 Water Inflow \_\_\_\_\_ (Bbls. per Day)

## RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)  
 Type of Tank

SKIM TANK 15 X 15 CVD, 100% oil CVD

PIT No. 1 40' x 40' Not CVD, Water Clean

PIT NO. 2 \_\_\_\_\_

PIT NO. 3 \_\_\_\_\_

ADDITIONAL PITS \_\_\_\_\_

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety  
 Conditions, Etc.)

Pits Not Lined

RECOMMENDED ACTION (If Required) \_\_\_\_\_



INSPECTOR James

117817