

NMU 11-12H

Inspection# 673402922

Cuttings in left corner of photo.



Cuttings on location.



Rills coming onto
location.



Rills coming onto
location.

