



STATE OF  
COLORADO

EnviroScan - DNR, OGCC <dnr\_ogcc.enviroscan@state.co.us>

Facility: 116568  
Document #: 2211658  
Date: 02/24/2016

## Fwd: BW Musser 1- Facility ID #116568

1 message

Neidel - DNR, Kris <kris.neidel@state.co.us>

Wed, Feb 24, 2016 at 4:40 PM

To: OGCC EnviroScan - DNR <dnr\_ogcc.enviroscan@state.co.us>

Document Name(s)		
Document Number	(leave blank if not already assigned)	
Date Received		
Is data entry needed?	NO	
Indexing Information	Unique ID Type	Unique ID Number
First	Remediation (REM)	
Second	Facility ID (FAC)	116568
Third*	NOAV	
Additional Instructions	please upload this email as "request for facility closure"	

Kris Neidel  
Environmental Protection Specialist Northwest Area  
Colorado Oil and Gas Conservation Commission  
Office 970-871-1963  
Cell 970-846-5097



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Kris Neidel  
Environmental Protection Specialist Northwest Area  
Colorado Oil and Gas Conservation Commission  
Office 970-871-1963  
Cell 970-846-5097



Kris Neidel  
Environmental Protection Specialist Northwest Area  
Colorado Oil and Gas Conservation Commission  
Office 970-871-1963  
Cell 970-846-5097



----- Forwarded message -----

From: **April Stegall** <April.Stegall@questar.com>  
Date: Tue, Feb 16, 2016 at 11:41 AM  
Subject: BW Musser 1- Facility ID #116568  
To: "kris.neidel@state.co.us" <kris.neidel@state.co.us>  
Cc: Tammy Fredrickson <Tammy.Fredrickson@questar.com>

Kris,

Based on the following information, I don't believe that there was in fact a pit on BW Musser 1:

Google Earth historic imagery 1993-2014 shows no visible pit on location, see attachment.

I could not find a site security diagram in our files that shows a pit on location. I've attached the oldest drawing that we have in our files.

COGCC database turned up one inspection for the location in 1985, it is noted that there is no visible pit on location, see attachment.

I've also attached the blanket pit permit. Because it isn't clear in the contents of the permit which location have pits, it seems as though it was assumed that there were pits on every Powder wash location.

Speaking to Ray Hollander, Chief Operator in the Powder wash field with 20+ years, he also has no recollection of there ever being a pit on that location.

I'm requesting that Facility ID #116568 be closed, as I believe it was created in error.

Let me know if there is any other information I can provide.

Thank you!

April Stegall

Reclamation Agent


P.O. Box 458 ; 2221 Westgate, Rock Springs, WY 82901



# BW Musser 1

historic imagery-1993

## Legend

 BW MUSSER 1

BW MUSSER 1 

Google<sup>™</sup> earth

Image U.S. Geological Survey



100 ft




# BW Musser 1

historic imagery-2005

## Legend

 BW MUSSER 1

BW MUSSER 1 



100 ft

Google earth


Image USDA Farm Service Agency



# BW Musser 1

historic imagery-2006

## Legend

 BW MUSSER 1

BW MUSSER 1 

Google earth

Imagery USDA Farm Service Agency




100 ft



# BW Musser 1

historic imagery-2011

## Legend

 BW MUSSER 1

BW MUSSER 1 

Google earth

Image USDA Farm Service Agency



100 ft



# BW Musser 1

historic imagery-2014

## Legend

 BW MUSSER 1

BW MUSSER 1 


Google earth



100 ft



B.W. Musser #1  
 NW NE Sec 5-11-97  
 D-038749 - a  
 Wexpro Co Operator  
 Lot #6



Legend

- ⊕ Gas Meter
- ⌵ Valve
- Above Ground
- Undergroun





**Wexpro Company**  
1955 Blairtown Road  
P. O. Box 458  
Rock Springs, WY 82902  
Tel 307-352-7514  
Fax 307-352-7575

**Tammy Fredrickson**  
Field Production Administration

January 8, 2008

Bureau of Land Management  
Little Snake Field Office  
455 Emerson St.  
Craig, CO 81625

Re: BW Musser #1  
NW NE 5-11N-97W  
Lease No.: D-038749A  
Moffat County, Colorado

Gentlemen:

In accordance with the Onshore Order No. 3, Site Security Regulations, submitted herewith is a site facilities diagram for the above captioned facility.

This site facility diagram is part of the Powder Wash Plan. The Site Security Plan may be reviewed at the Wexpro Company, Powder Wash Plant office, Monday through Friday, 8:00 a.m. to 4:00 p.m.

If you require further information, please contact me.

Sincerely,

Tammy Fredrickson  
Office Administrator II

tlf/enc

cc: J. P. Lison (RSW86)  
J. Chen (QB333)  
Regulatory Affairs  
Inspection Files