

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
02/25/2016  
Document Number:  
666801965  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>284629</u>	<u>335068</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>PO BOX 370</u>
City:	<u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

**Compliance Summary:**

QtrQtr: SWSW Sec: 15 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/10/2014	666800404	PR	PR	SATISFACTORY			No
03/17/2010	200239121	PR	PR	SATISFACTORY			No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR	<input checked="" type="checkbox"/>
284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR	<input checked="" type="checkbox"/>
284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR	<input checked="" type="checkbox"/>
284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR	<input checked="" type="checkbox"/>
284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR	<input checked="" type="checkbox"/>
284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR	<input checked="" type="checkbox"/>
284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR	<input checked="" type="checkbox"/>
284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR	<input checked="" type="checkbox"/>
284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR	<input checked="" type="checkbox"/>

284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR	<input checked="" type="checkbox"/>
284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR	<input checked="" type="checkbox"/>
284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR	<input checked="" type="checkbox"/>
284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR	<input checked="" type="checkbox"/>
294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1904-002		

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Horizontal Heated Separator	# 14	Satisfactory/Action Required: SATISFACTORY
Comment		

Corrective Action		Date:
Type: Plunger Lift	# 14	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	,
S/AR	SATISFACTORY		Comment: Centralized battery	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,
S/AR	SATISFACTORY		Comment: Centralized battery	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

**Facilities:**       New Tank      Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	39.520550,-107.880030
S/AR	SATISFACTORY		Comment:	
Corrective Action:			Corrective Date:	

Paint

Inspector Name: Murray, Richard

Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

**Venting:**

Yes/No	YES
Comment	Bradenhead valves open

**Flaring:**

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 284629

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 210475 Type: WELL API Number: 045-06231 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 284621 Type: WELL API Number: 045-12244 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 284622 Type: WELL API Number: 045-12243 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 284623	Type: WELL	API Number: 045-12242	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284624	Type: WELL	API Number: 045-12241	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284625	Type: WELL	API Number: 045-12240	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284626	Type: WELL	API Number: 045-12239	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284627	Type: WELL	API Number: 045-12238	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284628	Type: WELL	API Number: 045-12237	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284629	Type: WELL	API Number: 045-12236	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284630	Type: WELL	API Number: 045-12235	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284641	Type: WELL	API Number: 045-12246	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 284642	Type: WELL	API Number: 045-12245	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				
Facility ID: 294713	Type: WELL	API Number: 045-15577	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: <span style="color: red;">Plunger lift</span>				

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB):  N   
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels):  YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_  
 Comment: \_\_\_\_\_

1003a. Waste and Debris removed?  Pass   
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite?  Pass   
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?  Pass   
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_  
 CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Inspector Name: Murray, Richard

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Sediment Traps	Pass					
Slope Roughening	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Retention Ponds	Pass			
Ditches	Pass					

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT