



photo 1: Facing east along the access road toward the location.



photo 2: Facing east toward the location.



photo 3: Erosion channel transporting sediment off the northwest corner of the location.



photo 4: North side of the location facing east.



photo 5: Signs of erosion off the north side of the location.



photo 6: Northeast corner of the location facing south.



photo 7: Southeast corner of the location facing west.



photo 8: Signs of erosion off the southeast corner of the location.