

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing South. Evidence of well location in agricultural field. Not properly recontoured. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing Southwest. Evidence of well location in agricultural field. Not properly recontoured. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing West. Evidence of well location in agricultural field. Not properly recontoured. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing Northwest. Evidence of well location in agricultural field. Not properly recontoured. Need to monitor crop growth next growing season.