

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. Bare spots that appear to lack vegetative growth. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. Bare spots that appear to lack vegetative growth. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. Bare spots that appear to lack vegetative growth. Need to monitor crop growth next growing season.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. Bare spots that appear to lack vegetative growth. Need to monitor crop growth next growing season.