

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2016

Document Number:

680100545

Overall Inspection:

SATISFACTORY w/ CMT  
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	293939	335544	Colby, Lou	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 602 SAWYER STREET #710City: HOUSTON State: TX Zip: 77007

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Eisinger, Chris		chris.eisinger@state.co.us	
Freeman, Sarah		sarah.freeman@state.co.us	
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	
Bleil, Rob	970-329-4373	rbleil@ursaresources.com	

**Compliance Summary:**QtrQtr: NESW Sec: 13 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/19/2008	200201626	PR	WO	SATISFACTORY			No

**Inspector Comment:**

This is a Reclamation Focused Inspection being Conducted to Document Status, placement and conditions of AL and XX Wells on Location to stimulate filing of forms & Status updates necessary to have records reflect current field conditions. There are a total of Seventeen Wells on Location, 11 PR, 1WO, 2 AL, and 3 XX. The Five AL/XX all have Conductor set (XX Well A10 has cellar but Conductor is not visible) Two of the XX are actually AL, permits AB 11/19/13. All were reported at Abandonment "Conductor Not Set" except for AL A13(045-15169). The XX A6 has a current Permit, Expires 2017. On COGCC GIS two XX Wells are not represented and one XX Identified in place of PR Well A16 which is not on the Map. Refer to Table & Photos Attached.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
293933	WELL	PR	07/18/2013	GW	045-15166	NORCROSS A16	PR	<input type="checkbox"/>
293934	WELL	PR	07/18/2013	GW	045-15167	NORCROSS A15	PR	<input type="checkbox"/>
293937	WELL	PR	06/13/2011	GW	045-15168	NORCROSS A14	PR	<input type="checkbox"/>
293938	WELL	AL	11/13/2014	LO	045-15169	NORCROSS A13	RI	<input checked="" type="checkbox"/>
293939	WELL	XX	10/05/2011	LO	045-15170	NORCROSS A12	RI	<input checked="" type="checkbox"/>
293940	WELL	PR	07/18/2013	GW	045-15171	NORCROSS A11	PR	<input type="checkbox"/>

Inspector Name: Colby, Lou

293941	WELL	XX	01/26/2015	LO	045-15172	NORCROSS A10	RI	<input checked="" type="checkbox"/>
293942	WELL	PR	07/18/2013	GW	045-15173	NORCROSS A9	PR	<input type="checkbox"/>
293943	WELL	PR	12/13/2007	GW	045-15174	NORCROSS A8	PR	<input type="checkbox"/>
293944	WELL	PR	03/11/2009	GW	045-15175	NORCROSS A7	PR	<input type="checkbox"/>
293945	WELL	XX	10/05/2011	LO	045-15176	NORCROSS A6	RI	<input checked="" type="checkbox"/>
293946	WELL	PR	01/26/2009	GW	045-15177	NORCROSS A5	PR	<input type="checkbox"/>
293947	WELL	PR	12/13/2007	GW	045-15178	NORCROSS A4	PR	<input type="checkbox"/>
293948	WELL	PR	07/28/2010	GW	045-15179	NORCROSS A3	PR	<input type="checkbox"/>
293949	WELL	PR	12/13/2007	GW	045-15180	NORCROSS A2	PR	<input type="checkbox"/>
293950	WELL	WO	04/26/2012	SI	045-15181	NORCROSS A1	WO	<input type="checkbox"/>
298337	WELL	AL	11/13/2014	LO	045-17143	NORCROSS A17	RI	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Recommended to cover Cellars completely of all AL/XX Wells that have no Well head extending through grating; it would greatly enhance Wildlife and Workplace Safety. Refer to Photos attached.		

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Equipment:</b>				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

<b>Venting:</b>	
Yes/No	
Comment	

<b>Flaring:</b>			
Type	Satisfactory/Action Required		
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 293939

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 293938 Type: WELL API Number: 045-15169 Status: AL Insp. Status: RI

Facility ID: 293939 Type: WELL API Number: 045-15170 Status: XX Insp. Status: RI

Facility ID: 293941 Type: WELL API Number: 045-15172 Status: XX Insp. Status: RI

Facility ID: 293945 Type: WELL API Number: 045-15176 Status: XX Insp. Status: RI

Facility ID: 298337 Type: WELL API Number: 045-17143 Status: AL Insp. Status: RI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Inspector Name: Colby, Lou

Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Recommended to cover Cellars completely of all AL/XX Wells that have no Well head extending through grating; it would greatly enhance Wildlife and Workplace Safety. Refer to Photos attached.	colbyl	03/01/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680100569	Well Lay Out Table	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796889">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796889</a>

680100570	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796890">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3796890</a>
-----------	-------------------	---