

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2016

Document Number:

673802934

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 332169 | 332169 | Gomez, Jason | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Compliance Summary:QtrQtr: SESE Sec: 25 Twp: 5N Range: 67W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 270689 | WELL | PR | 03/23/2005 | GW | 123-21927 | BOOTH N 25-16 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| | | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Inspector Name: Gomez, Jason

| | | | | |
|----------------------|--------------|--|--|--|
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-------|------------------------------|-------------------|-------------------|---------|
| Other | SATISFACTORY | Wire/Tank Battery | | |
| Panel | SATISFACTORY | wellhead | | |

Equipment:

| | | | |
|-----------------------------------|-----|-------------------------------|--------------|
| Type: Horizontal Heated Separator | # 2 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Gas Meter Run | # 2 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Bird Protectors | # 2 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |
| Type: Emission Control Device | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | | | |
| Corrective Action | | | Date: |

Facilities:

☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|-----------|---|----------|-----------|-----------------------|
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | 40.365080,-108.832310 |

S/AR SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Inspector Name: Gomez, Jason

| | | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

Facilities: ☐ New Tank Tank ID: _____

| | | | | | |
|--------------------|--------------|----------|---------------------|-----------------------|--|
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 2 | <50 BBLS | CONCRETE SUMP/VAULT | 40.365080,-104.832310 | |
| S/AR | SATISFACTORY | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |

Paint

| | | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|--|
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 332169

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 270689 Type: WELL API Number: 123-21927 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Pressure Monitored

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Gomez, Jason

| | | |
|---|--|----------------------|
| Comment: <input style="width: 700px;" type="text"/> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |
| Water Well: | | |
| | | Lat _____ Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |
| Field Parameters: | | |
| <input style="width: 300px;" type="text"/> | | |
| Sample Location: <input style="width: 400px;" type="text"/> | | |
| Emission Control Burner (ECB): Y _____ | | |
| Comment: _____ | | |
| Pilot: ON _____ | Wildlife Protection Devices (fired vessels): YES _____ | |

Reclamation - Storm Water - Pit

Interim Reclamation:

| | |
|--|---|
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <input style="width: 750px;" type="text"/> | |
| 1003a. Waste and Debris removed? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Unused or unneeded equipment onsite? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Pit, cellars, rat holes and other bores closed? <u>Pass</u> | |
| CM _____ | |
| CA _____ | CA Date _____ |
| Guy line anchors marked? _____ | |
| CM _____ | |
| CA _____ | CA Date _____ |
| 1003b. Area no longer in use? <u>Pass</u> | Production areas stabilized ? <u>Pass</u> |
| 1003c. Compacted areas have been cross ripped? _____ | |
| 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ | |
| Cuttings management: _____ | |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ | |
| Production areas have been stabilized? <u>Pass</u> | Segregated soils have been replaced? <u>Pass</u> |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |
| Top soil replaced <u>Pass</u> | Recontoured <u>Pass</u> Perennial forage re-established _____ |

Inspector Name: Gomez, Jason

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT