

Interim Reclamation Inspection

3/3/2016

Operator: Whiting Oil and Gas

Location ID: 425520

Weld County, CO

SWSE Section 18 T10N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from pump, facing south. Photo shows sign missing at wellhead.



03.03.2016 10:33

Figure 2: Photo taken from pump, facing south. Photo shows sign missing at wellhead.



03.03.2016 10:34

Figure 3: Photo taken from southeast end of project area, facing northwest. Photo shows trash debris near soil stockpile.