

Interim Reclamation Inspection

3/3/2016

Operator: Whiting Oil and Gas

Location ID: 433919

Weld County, CO

NENE Section 21 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from the southern end of location, facing southwest. Photo shows trash debris (appears to be a tarp liner) documented in FIR #682500410.



Figure 2: Photo taken from the south end of location, facing southeast. Photo shows portable toilets improperly staked down and knocked over.



Figure 3: Photo taken at knocked over portable toilet on the south end of location. Photo shows soils possibly contaminated by chemicals spilled from knocked over portable toilet.



Figure 4: Photo taken from the west end of the location, facing southwest. Photo shows wattles in disrepair.