

Inspection Photos  
3/3/16  
Facility #274311  
Dale 44-36 API 05-071-07908



Figure 1 – Lease sign



Figure 2 – Pit and Signage





Figure 3 – Looking south



Figure 4 – Looking south at pit. Partially buried trash in pit.





Figure 5 – Looking north at well pad



Figure 6 – Looking east at well pad. Fencing material on ground in bottom left of picture.