

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2016

Document Number:

680600470

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 216488      | 326435 | ROY, CATHERINE  | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email                                | Comment         |
|--------------|-------|--------------------------------------|-----------------|
| , General    |       | COGCCInspectionReports@wpxenergy.com | All Inspections |

**Compliance Summary:**QtrQtr: SENW Sec: 10 Twp: 33N Range: 8W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/27/2016 | 685300003 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 08/01/2014 | 674900103 | PR         | EI          | SATISFACTORY                  |          |                | No              |
| 05/05/2009 | 200209622 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 01/18/2006 | 200087902 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 01/27/2004 | 200052450 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 02/11/2003 | 200036319 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 07/17/2001 | 200019537 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 02/15/2000 | 200004442 | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |
| 03/04/1998 | 500150705 | PR         | PR          |                               |          | Pass           | No              |
| 01/28/1998 | 500150706 | PR         | PR          |                               |          | Pass           | No              |
| 01/28/1998 | 500150704 | PR         | PR          |                               |          | Pass           | No              |

**Inspector Comment:**

This is an interim reclamation and stormwater inspection. Location is surrounded by land disturbing activities from recent BP drilling operations. It is the responsibility of WPX to coordinate with BP to ensure the location is properly reclaimed.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 216488      | WELL | PR     | 01/10/2012  | GW         | 067-08094 | IGNACIO 33-8 #027 | RI          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

Inspector Name: ROY, CATHERINE

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

### Location

#### Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
|      |                              |         |                   |      |

#### Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

Emergency Contact Number (S/AR): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

#### Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

#### Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
|      |                              |         |                   |         |

#### Equipment:

| Type:             | # | Satisfactory/Action Required: |             |
|-------------------|---|-------------------------------|-------------|
| Comment           |   |                               |             |
| Corrective Action |   |                               | Date: _____ |

#### Venting:

| Yes/No  |  |
|---------|--|
| Comment |  |

#### Flaring:

| Type               | Satisfactory/Action Required |                            |
|--------------------|------------------------------|----------------------------|
| Comment:           |                              |                            |
| Corrective Action: |                              | Correct Action Date: _____ |

**Predrill**

Location ID: 216488

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 216488 Type: WELL API Number: 067-08094 Status: PR Insp. Status: RI

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

|                                      |  |             |
|--------------------------------------|--|-------------|
| DWR Receipt Num: _____               | Owner Name: _____                                  | GPS : _____ |
| <b>Field Parameters:</b>             |  |             |
|                                      |  |             |
| Sample Location: _____               |  |             |
|                                      |  |             |
| Emission Control Burner (ECB): _____ |  |             |
| Comment: _____                       |  |             |
| Pilot: _____                         | Wildlife Protection Devices (fired vessels): _____ |             |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Production facilities are surrounded by jersey barriers. Location is surrounded by pinion-juniper woodland.

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

Inspector Name: ROY, CATHERINE

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_

Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 680600474    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3800495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3800495</a> |