

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/08/2016
Document Number:
666801981
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|--------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>89063</u> | <u>334792</u> | <u>Murray, Richard</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Compliance Summary:

QtrQtr: NENW Sec: 17 Twp: 7S Range: 92W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 12/06/2006 | 200101436 | PR | PR | SATISFACTORY | I | Pass | No |
| 10/05/1999 | 500143232 | PR | PR | | | Pass | No |

Inspector Comment:

Action required items noted in previous inspection have been satisfied

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 89063 | WELL | PR | 02/15/2003 | GW | 045-07393 | COUEY 17-7 | PR <input checked="" type="checkbox"/> |
| 89067 | WELL | PR | 06/26/2000 | GW | 045-07397 | COUEY 17-2 | PR <input checked="" type="checkbox"/> |
| 259884 | WELL | PR | 02/02/2004 | GW | 045-07794 | COUEY 17-2A | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| BATTERY | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |
| CONTAINERS | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Equipment: | | | | | |
|-----------------------------------|-----|-------------------------------|--------------|-------|--|
| Type: Plunger Lift | # 3 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Horizontal Heated Separator | # 3 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |

| Facilities: | | | | | |
|-----------------------------------|--------------|----------------|-----------|-----------------------|--|
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | | |
| Contents | # | Capacity | Type | SE GPS | |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | 39.451977,-107.690983 | |
| S/AR | SATISFACTORY | Comment: _____ | | | |
| Corrective Action: | | | | Corrective Date: | |

Inspector Name: Murray, Richard

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|----------|---------------------|------------------|
| METHANOL | 1 | 1000 GAL | STEEL AST | , |
| S/AR | SATISFACTORY | Comment: | Centralized battery | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | |
|--------------------|--|------------------------------|
| Type | | Satisfactory/Action Required |
| Comment: | | |
| Corrective Action: | | Correct Action Date: |

Predrill

Location ID: 89063

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 89063 Type: WELL API Number: 045-07393 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 89067 Type: WELL API Number: 045-07397 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 259884 Type: WELL API Number: 045-07794 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____
1003a. Waste and Debris removed? Pass
CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass
CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass
CM _____
CA _____ CA Date _____
Guy line anchors marked? _____
CM _____
CA _____ CA Date _____
1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | Pass | | | |
| Ditches | Pass | | | | | |
| Seeding | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT