

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/08/2016
Document Number:
666801983
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>264995</u>	<u>334922</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou	970-989-4402	lou.colby@state.co.us	Area Reclamation Specialist
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr: NENW Sec: 21 Twp: 7S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/28/2011	200298441	PR	SI	ACTION REQUIRED			Yes
08/11/2010	200266584	PR	SI	SATISFACTORY			Yes
07/22/2003	200046870	PR	WO	SATISFACTORY		Pass	No

Inspector Comment:

Wells are ready for final reclamation inspection

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159215	UIC DISPOSAL	AC	06/06/2008		-	BUERGER DISPOSAL #2	AC <input type="checkbox"/>
159216	UIC DISPOSAL	AC	06/06/2008		-	BUERGER DISPOSAL #1	AC <input type="checkbox"/>
264989	WELL	PA	04/03/2014	GW	045-08971	BUERGER 16-14C (C21)	PA <input checked="" type="checkbox"/>
264994	WELL	PA	04/03/2014	DSPW	045-08973	BUERGER DISPOSAL 1	PA <input checked="" type="checkbox"/>
264995	WELL	PA	03/31/2014	GW	045-08972	BUERGER 16-15C (C21)	PA <input checked="" type="checkbox"/>
265380	WELL	PA	04/04/2014	DSPW	045-09003	BUERGER DISPOSAL 2	PA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 264995

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 264989 Type: WELL API Number: 045-08971 Status: PA Insp. Status: PA

Workover

Comment: Well was plugged in 2014

Facility ID: 264994 Type: WELL API Number: 045-08973 Status: PA Insp. Status: PA

Workover

Comment: Well was plugged in 2014

Facility ID: 264995 Type: WELL API Number: 045-08972 Status: PA Insp. Status: PA

Workover

Comment: Well was plugged in 2014

Facility ID: 265380 Type: WELL API Number: 045-09003 Status: PA Insp. Status: PA

Workover

Comment: Well was plugged in 2014

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed? Pass

CM CA CA Date

Unused or unneeded equipment onsite? Pass

CM CA CA Date

Pit, cellars, rat holes and other bores closed? Pass

CM CA CA Date

Guy line anchors marked? Pass

CM CA CA Date

Inspector Name: Murray, Richard

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

Inspector Name: Murray, Richard

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666801984	encana	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3801601