

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
03/07/2016
Document Number:
673712836
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 417993 | 417994 | Sherman, Susan | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 10489
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
Address: 2016 GRAND AVENUE #A
City: BILLINGS State: MT Zip: 59102

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|---------------------------|---------|
| DAVIS, LONI | (970) 332-3585 | ldavis@augustusenergy.com | |

Compliance Summary:

QtrQtr: NWSW Sec: 1 Twp: 1S Range: 44W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 03/14/2012 | 663900777 | XX | WO | SATISFACTORY | P | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 417993 | WELL | WO | 02/22/2011 | SI | 125-11884 | BROPHY 01-12 | WO <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|---------------------------------|-------------------------|---------------------|--------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: <u>1</u> | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: <u>1</u> | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: <u>1</u> |
| Electric Generators: _____ | Gas Pipeline: <u>1</u> | Oil Pipeline: _____ | Water Pipeline: <u>1</u> |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| OTHER | SATISFACTORY | on meter house @ CR 29 | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
| | | | | |

Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|------------------------------|--------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | steel panels | | |

Equipment:

| | | | |
|---------------------------|---|-------------------------------|--------------|
| Type: Ancillary equipment | # 2 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | solar panel and radio telemetry | | |
| Corrective Action | | Date: | |
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | shed, GPS 39.99199, -102.26199, digital | | |
| Corrective Action | | Date: | |
| Type: Vertical Separator | # 2 | Satisfactory/Action Required: | SATISFACTORY |
| Comment | partially buried | | |
| Corrective Action | | Date: | |

Venting:

| | |
|---------|--|
| Yes/No | |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 417993

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: SATISFACTORY **Comment:** No problems seen.

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 417993 Type: WELL API Number: 125-11884 Status: WO Insp. Status: WO

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: MIT passed 3/14/2012.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: DRY LAND
 Comment: wheat

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Inspector Name: Sherman, Susan

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR Corrective Date: _____

Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------|---|
| 673712846 | Augustus Brophy 01-12 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3801667 |