

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API 123-25680.

Interim Reclamation Inspection



Photo 2. Need to comply with Rule 1003 e (1) and remove/control invasion of undesirable species.

Interim Reclamation Inspection



Photo 3. Photo taken of PR well sign for API 123-13697.

Interim Reclamation Inspection



Photo 4. Need to comply with Rule 1003 e (1) and remove/control invasion of undesirable species.