



**photo 1:** Aerial image of the location taken on 10/11/2015.



**photo 2:** Facing east along the former access road toward the location.



**photo 3:** West side of the location facing northeast. There is no evidence of crop growth in this area.



**photo 4:** Facing east toward the location. There is no evidence of crop growth in this area.



**photo 5:** Center of the location facing west. There is no evidence of crop growth in this area approx. 90'x50' in size.



**photo 6:** Evidence of surrounding crop growth.



photo 7: Aerial image showing location and pipe riser found to the east.



Photo 8: Pipe riser found east of the location. Lat/Long:38.41642,-103.00220.